

RECALL NOTICE

Marker Recalls 2017-2018 Kingpin 10 and 13 Touring bindings toe parts.



Kingpin 10 and Kingpin 13 Gold





Kingpin 10 and Kingpin 13 Copper

Hazard: The Pin in the toe piece can break under rare circumstances. This can lead to reduced release/retention and can result in a fall hazard.

Recalled Products: 2017-2018 Kingpin 10 and 13 Touring bindings with serial numbers in the range seen below:

 <p>With this serial number on the heel, a Marker Authorized Retailer can confirm if your binding is affected or not. If your serial number is in the range listed below, you should replace the toe pieces.</p> <p>Kingpin 10 serial # 337804 - 418632</p> <p>Kingpin 13 serial # 337798 - 411728</p>	 <p>Toe pieces with these logo treatments are affected by the recall</p> 
---	--

 <p>Toe pieces with these logo treatments are not affected by the recall</p> 

Remedy: Stop using these bindings and return them to a Marker Authorized Retailer to determine if they are covered by this recall. Toe pieces of recalled bindings will be replaced at no charge. Skiers should bring their boots to be sure their bindings are adjusted correctly.

For additional information, call Marker customer service at 800-453-3862 Monday through Friday 8:30 a.m. to 5:00 p.m., or send an email to kingpin.exchange@mdv-usa.com, or visit www.markerusa.com.

This recall is being conducted in cooperation with the U.S. Consumer Product Safety Commission

* Post Until March 31, 2019